

**GREGORY S. BELL** Lieutenant Governor

## State of Utah

## DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

## **Inspection Report Minerals Regulatory Program**

January 6, 2010

Reviewed:	1766

Mine Name: Iron Mountain Riprap	Inspection Date: May 20, 2009 Time: 8AM		
Operator Name: Iron County			
Inspector(s): T Munson			
Other Participants: none	Mine Status: Ins		
Elements of Inspection	Evaluated	Comment	Enforcemen
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, highwalls)</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control, safety)</li> <li>Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</li> <li>Soils</li> <li>Revegetation</li> </ol>			
Bond Amount: \$2,500,00 Peri	mit Fees: Curre	nt	

**Purpose of Inspection:** Site inspection

**Inspection Summary:** Site was actively being mined. There was one person who loaded trucks full of riprap from the base of the old Iron Mine waste piles. The site was disturbed by a trackhoe harvesting rock riprap from the face of the waste piles and truck traffic in and out from the base of the piles to the highway.

Photos were taken to document site conditions.

## **Conclusions and Recommendations:**

The site be subject to regular inspections.

**Inspector's Signature** 

TM:vs

cc: Iron County, 82 N 100 E Ste 104, Cedar City, Ut 84720-2807



